

Work Order ID 75243***75243***

Page 1

October-19-11 1:29:16 PM

Item ID: D350-607-511

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Quick Release Basket Mounting Installation

Start Date: 19/10/2011 Start Qty: 1.00

1

Cust Item ID:

Required Date: 07/11/2011 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: MLJ Date: 11/10/11

Tooling:

Date:

Run Start ***NR1***

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D350-607-3

A

100

0.00

100

DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPPD350-607-511 CHG002

5 u/10/26

for MLJ 11-10-25
(1)

140

Pick Kit

0.00

140

Packaging

Memo

0.00

Packaging

Sp 11 - 10 - 26.

150

QC4- 100% Inspect kits for completeness

0.00

150

QC

Memo

0.00

Quality Control

5 u/10/26

40

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 75243***75243***

Page 2

October-19-11 1:29:16 PM

Item ID: D350-607-511

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Quick Release Basket Mounting Installation

Start Date: 19/10/2011 Start Qty: 1.00

1

Cust Item ID:

Required Date: 07/11/2011 Req'd Qty: 1.00

1

Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start ***NR1***

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

160

0.00

160

Packaging

RCOB

Packaging

Memo

0.00

Packaging

Identify and pack for shipping as per PPP D350-607-511

Location: PIC

11/10/27

170

0.00

170

QC21- Final Inspection - Work Order Release

QC

Memo

0.00

Quality Control

11/10/27

ME
11-10-26

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

October-19-11 1:29:22 PM

Page 1

Work Order ID: 75243

75243

Parent Item: D350-607-511

D350-607-511

Parent Item Name: Quick Release Basket Mounting Installation

Start Date: 19/10/2011

Required Date: 07/11/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP REV:A NEW ISSUE 10-06-28 JLM VERIFIED BY: LL

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3910-3		Manufactured	No			140	Each	14.0000	4	4			

D3910-3

Crosstube Lug

**

Location

Loc Qty

Loc Code

st507

14

73526

14

D3984

Manufactured

No

140

f

330.5900

2

2

D3984

Rubber Extrusion, Crosstube

**

Location

Loc Qty

Loc Code

ST411

330.59

53707

330.59

CUT (8) AT 3.00" LONG

D4148-041

Manufactured

No

140

Each

3.0000

1

1

D4148-041

Crosstube Lug Assembly, Fwd

**

Location

Loc Qty

Loc Code

ST468

3

70157

3

D4149-041

Manufactured

No

140

Each

2.0000

1

1

D4149-041

Crosstube Lug Assembly, Aft

**

Location

Loc Qty

Loc Code

ST468

2

70159

2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

October-19-11 1:29:22 PM

Page 2

Work Order ID: 75243

75243

Parent Item: D350-607-511

D350-607-511

Parent Item Name: Quick Release Basket Mounting Installation

Start Date: 19/10/2011

Required Date: 07/11/2011

Start Qty: 1.00

Required Qty: 1.00

AN4-14A
AN4-14A
Bolt

Purchased No

140 Each

263.0000

16 16

**

Sp.

Location

Loc Qty

Loc Code

ST358

263

118628

100

118706

63

119127

100

MS21042L4

Purchased No

140 Each

14,038.00

16 16

**

Sp.

MS21042L 4
Nut

Location

Loc Qty

Loc Code

ST300

3038

117441

51

117601

537

117885

56

118451

1394

118927

1000

ST516

6000

119017

6000

ST518

5000

119075

5000

NAS1149F0432P

Purchased No

140 Each

90.0000

32 32

**

Sp 11-10-26.

NAS1149F0432P
Washer

Location

Loc Qty

Loc Code

ST275

90

119109

90

32x

October-19-11 1:29:22 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

REFERENCE ONLY

DART AEROSPACE LTD.

D350-607-3
Page 17 of 19

4.0 WEIGHT AND BALANCE

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
D350-607-541 (Standard Basket)	80.7 lb 36.6 kg	± 49.1 in ± 1.25 m	± 3962 in-lb ± 45.8 m-kg	135 in 3.43 m	10895 in-lb 125.5 m-kg
D350-607-543 (Lightweight Basket)	65.7 lb 29.8 kg	± 49.1 in ± 1.25 m	± 3226 in-lb ± 37.3 m-kg	135 in 3.43 m	8870 in-lb 102.2 m-kg
D350-607-545 (Standard Basket)	58.7 lb 26.2 kg	± 49.1 in ± 1.25m	± 2882 in-lb ± 32.8 m-kg	135 in 3.43 m	7925 in-lb 89.9 m-kg
D350-607-547 (Lightweight Basket)	47.7 lb 21.6 kg	± 49.1 in ± 1.25 m	± 2342 in-lb ± 27.0 m-kg	135 in 3.43 m	6440 in-lb 74.1 m-kg
D350-607-511 (Quick Release Basket Mounting Kit)	7.2 lb 3.3 kg	± 36.9 in ± 0.94 m	± 266 in-lb ± 3.1 m-kg	135 in 3.43 m	972 in-lb 11.3 m-kg

5.0 PARTS LIST

QTY -541	QTY -543	QTY -545	QTY -547	QTY -511	QTY -501	PART NUMBER	DESCRIPTION
X						D350-607-541	HELI-UTILITY-BASKET
	X					D350-607-543	HELI-UTILITY-BASKET
		X				D350-607-545	HELI-UTILITY-BASKET
			X			D350-607-547	HELI-UTILITY-BASKET
1	1	1	1	X		D350-607-511	QUICK RELEASE BASKET MOUNTING KIT
					X	D350-607-501	CONVERSION KIT
1	1	1	1		1	D2690-6	LANYARD
				4	4	D3910-3	X-TUBE LUG
1	1	1	1		1	D3912-041	EYEBOLT RECEIVER ASSY
				8	8	D3984-030	RUBBER EXTRUSION, X-TUBE
1						D4030-041	LONG BASKET ASSY
	1					D4030-043	LONG BASKET ASSY, LIGHTWEIGHT
		1				D4032-041	SHORT BASKET ASSY
			1			D4032-043	SHORT BASKET ASSY, LIGHTWEIGHT
1	1	1	1		1	D4085-3	PLACARD-INSTRUCTIONS
1					1	D4086-200	PLACARD, MAX LOAD
	1				1	D4086-215	PLACARD, MAX LOAD
		1			1	D4086-220	PLACARD, MAX LOAD
			1		1	D4086-232	PLACARD, MAX LOAD
				1	1	D4148-041	FWD X-TUBE LUG ASSY
				1	1	D4149-041	AFT X-TUBE LUG ASSY
1	1	1	1		1	D4150-041	ATTACHMENT ARM ASSY
1	1	1	1		1	D4151-041	BASKET FWD HARDPOINT ASSY (LOWER)
1	1	1	1		1	D4151-043	BASKET FWD HARDPOINT ASSY (UPPER)
6	6	6	6		6	AN4-13A	BOLT
				16	16	AN4-14A	BOLT
1	1	1	1		1	AN4C15	BOLT
1	1	1	1		1	AN310C4	CASTELLATED NUT
1	1	1	1		1	MS17984-C413	QUICK RELEASE PIN
6	6	6	6	16	22	MS21042L4	NUT (OR MS21042-4)
1	1	1	1		1	MS24665-151	COTTER PIN
2	2	2	2		2	NAS1515H4L	WASHER
12	12	12	12	32	44	NAS1149F0432P	WASHER
3	3	3	3		3	NAS1149C0463R	WASHER

• COPYRIGHT © 2010 BY DART AEROSPACE LTD •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: A
Date: 10.06.28

